
DRILL 3/16 HOLES IN BACK
SEAL CABLE HOLES NOT USED WITH CORKS DIPPED IN VARNISH
DRILL AND TAP BOX 1/20
2 1/2 x 2 1/2 R. HEAD RIVETS
SECTION A-A
SECTION C-C
2-1/20 3/8 BRASS CAP SCREWS
4-5/8 x 3 1/2 leg screws
SERVICE POLE
SECTION B-B
HIGH
VOLTAGE
DANGER
PLAN OF SWITCH BOX DOOR
LETTERS TO BE CAST AND RAISED 1/4 IN DOOR
SCALE
CUTOUT BOX
FOR ELECTROLIER SERVICE LOCATIONS
CUTOUT ARRANGEMENT FOR TWO CIRCUITS SHOWN


DRILL 3/16 HOLES IN BACK
SEAL CABLE HOLES NOT USED WITH CORKS DIPPED IN VARNISH
DRILL AND TAP BOX 1/20
2 1/2 x 2 1/2 R. HEAD RIVETS
SECTION A-A
SECTION C-C
2-1/20 3/8 BRASS CAP SCREWS
4-5/8 x 3 1/2 leg screws
SERVICE POLE
SECTION B-B
HIGH
VOLTAGE
DANGER
PLAN OF SWITCH BOX DOOR
LETTERS TO BE CAST AND RAISED 1/4 IN DOOR
SCALE
CUTOUT BOX
FOR ELECTROLIER SERVICE LOCATIONS
CUTOUT ARRANGEMENT FOR TWO CIRCUITS SHOWN